


[DOWNLOAD](#)


Care and Operation, List of Parts; 75 H.P. Caterpillar . Tractor. Model A -Nvs.

By Peoria Holt Manufacturing Company

Rarebooksclub.com, United States, 2013. Paperback. Book Condition: New. 246 x 189 mm. Language: English . Brand New Book ***** Print on Demand *****.This historic book may have numerous typos and missing text. Purchasers can usually download a free scanned copy of the original book (without typos) from the publisher. Not indexed. Not illustrated. 1918 edition. Excerpt: . pump and fan belt and cause trouble. This point should be watched carefully and timing gear lubrication cut down if necessary. Too much oil to fan shaft may cause trouble by leaking from fan bearing and getting on belt. LUBRICATION OF WATER PUMP 1 5 1-The lubrication of the centrifugal pump is secured by a sight feed gravity oiler to the two bearings on the pump. Adjust oiler to two drops per minute. Use cylinder oil in sight feed oiler. RADIATOR 1 5 2-The radiator of the 75 is built up with 32 radiator sections. each section containing 3 copper, finned tubes 6262. The upper radiator section header 5027 and the lower radiator section header 5028 are made of brass. The upperradiator frame header 1339 and the lower radiator fraine header 1340 is made of cast iron, and is a part of the frame...



[READ ONLINE](#)
[5.83 MB]

Reviews

Undoubtedly, this is the best job by any article writer. This really is for all those who statte that there was not a worth reading. I am very easily can get a enjoyment of reading a published pdf.

-- **Rowena Leannon**

It in a of my personal favorite book. This is certainly for anyone who statte there had not been a worth studying. I found out this ebook from my i and dad advised this pdf to learn.

-- **Delphine Lebsack**